


STUDIECENTRUM VOOR KERNENERGIE CENTRE D'ETUDE DE L'ENERGIE NUCLEAIRE


Country report Belgium RROG 2019, Mainz





Copyright © 2019 SCK•CEN



Reactor core performance of BR2








- Design goal: thermal neutron flux up to 10¹⁵ n/cm²s
 - Achievement by
 - Compact core arrangement with central flux trap
 - Material choice: Be moderator and metallic uranium fuel
 - High overall core power (upgraded from 50 to 100MW in 1968)
 - Achievable flux levels (at mid plane in vessel)
 - Thermal flux: 7 10¹³ n/cm²s to 10¹⁵ n/cm²s
 - Fast flux (E>0.1MeV): 1 10¹³ n/cm²s to 6 10¹⁴ n/cm²s
- Allowable heat flux in primary coolant
 - 470W/cm² for the driver fuel plates
 - Demineralised water
 - Pressure to 1.2MPa, temperature 35-50°C
 - 10m/s flow velocity on fuel plate
 - Up to 600W/cm² can be allowed in experiments


Reactor core geometry



BR2 Overview

- Belgian Reactor 2 : in operation since 1963
 - Upgraded in 1968 to 100MW
 - Refurbishment in 1977-1980
 - Subject to decennial license review since 1986
 - Refurbished in 1995-1997
 - Refurbished 2015-2016
- Restarted on July 19, 2016
 - Requalification programme finalised
 - Periodic safety reassessment report delivered
 - 11 reactor cycles performed up to May 2019





Operational highlights

- 6 reactor cycles in 2018: 147 days of operation
- 5 reactor cycles in 2019 (scheduled): 163 days of operation
- Availability factor
 - 2018: 40%; actual 97% of planned realized
 - 2019: 44% planned (100% so far realized after 2 cycles)
 - 2020: aim to 200-210 days
- Utilisation
 - Large increase in demand for radio-isotopes and NTD-Si (capacity fully booked in 2019)
 - Material irradiations for fusion (W alloys) and RPV ageing
 - Fuel plate irradiations for MTR fuel qualification based on LEU
 - Requalification of LWR fuel pin irradiation capsule
- Large projects at SCK•CEN
 - Construction of MINERVA LINAC funded by Belgian government
 - NURA project integrating all activities on medical applications of nuclear technology


CLUSTERING KNOWHOW AND EXPERTISE WITHIN

THE FIELD OF RADIOPHARMACEUTICALS

С

R

0



Safety indicators 2018


- Radiological exposure of staff:
 - Collective dose:
 - Reactor operation staff (33): 18mSv (6 reactor cycles)
 - All works: 61,3mSv
 - Average dose:
 - Reactor operation staff average: 0,12mSv max individual 1,165mSv
 - Overall average: 0.5mSv max individual 2.3mSv

Emissions

	α	β	I	HT	HTO	Edelgas
	(Bq)	(Bq)	(Bq)	(Bq)	(Bq)	(Bq)
BR2 Jaarlijkse limiet	4,49E+03	3,48E+04	1,86E+06 2,03E+09	-	1,76E+12	2,19E+12 6,08E+14


- Utilisation factor: 40% in 2018
- Actual/planned operation in 2018: 97%

Dose evolution



Collectieve dosis Hp man.mSv

Emission evolution



- Operational feed from the RECALL material irradiation loop and incident reporting
 - Cycle 2/2018A (1 day commissioning test): feedback experience on accumulation and spreading of radio-activity in loop, mainly due to activation of Ar and Mn; electric heating quite weak to compensate for heat loss at nuclear heating of maximum 2W/g
 - Cycle 2/2018B: regular operation during 28 days
 - Cycle 03/2018: Reactor reverse due to low temperature in RECALL IPS – heating element broken
 - Root cause analysis:
 - Protection of heater in case of zero flow was wrongly programmed/not tested
 - Zero flow condition was triggered by high radiation in water return from IPS
 - High radiation due to stray resin particles and poor degassing of fresh water
 - Fresh water was needed due to leaking high pressure pumps

Ageing management

Primary loop inspections

- Indication of non acceptable defect in circumferential pipe to flange weld
 - Section at redundant primary pump taken out of service – no safety impact; operation with 3 primary pumps during cycle 03/2018
 - Pipe section replaced by stainless steel section during shut-down 04/2019
 - Designed according to ASME VIII code
 - New sealing material qualified with sufficient gamma dose margin
- Post extraction analysis:
 - No defect present (X-ray), UT indication due to weld repair (not documented)






Ageing management (2)


- Upgrade of emergency electrical feed
 - State of art technology rotating UPS + diesel generators
 - Obsolete technology of current generators difficult to maintain
 - Upgrade of resistance to hazards
 - Increased seismic resistance of building
 - Full separation of units with respect to fire hazard
 - Elimination of common cause failures
 - Redundant safety relevant components on common switchboards in old system
 - Full separation to independent and redundant lines in new system

New Powerhouse




- 6 fire compartments
 - 2 independent fire extinguishing systems
 - Genset: water + nitrogen
 - DUPS: inert gas
- 2 separated gensets and DUPS
- Compliant to modern environmental standards
- Secured building

Diesel replacement - main principle




Diesel replacement - main principle



Genset


Utility outage

Diesel replacement - main principle



Utility outages– Genset working

Start kinetics



Upgrade of electrical feed of vital network – old situation





Illustration of redistribution of redundant systems


Current feed	New Feed TGI (TI)	New Feed TGII (TII/TIII)	Current feed
TIII	E1	E2	TIII
TIII	J18-304	J18-303	TIII
TIII	J28-5-304	J28-5-303	TI
TIII	T52 (net2)	T52 (net1)	TIII
TII	J5-402	J5-401	TII
TII	J5-412	J5-411	TII
TII	J4-406	J4-405	TII
TII	J28-5-404	J28-5-403	TII
TII	Tfo21 (UPS-KZR)	UPS-KZR	TI
TI	J28-5-412	J28-5-411	TI
TI	Tfo30 (info-net)	Tfo29 (info-net)	TIII
TII-EX	TVB2	TVB1	TII
TII-EX	TXI (via TC1/17)	TXI	TII
TII-EX	CB20 (via CB118)	CB20	TII

New situation

- Old switchboard lay out → single point of failure
 Loss of switchboard T II
 - Loss of all users on TII and TIII
 - Loss of connection to 2 of 3 diesel generators
- Upgrade to 2 separated feeds (with option of coupling
 - Electrical common cause failure prevention
 - T I → new T I
 - T II + T III → new T II
 - Prevention of common cause failure by fire
 - New T I in separate room




Implementation plan



Driver fuel conversion HEU-LEU

3 step approach

- Modify geometry of HEU element
 - Increased meat thickness
- Qualification of LEU based system with evolutionary properties: 5,2g/cc silicide: flat plate irradiation
- Qualification of LEU lead test assemblies




COBRA HEU LTA description


	COBRA-HEU- Gd	COBRA-HEU-BSm	Standard FE
Enrichment ²³⁵ U [%]	93.0	93.0	93.0
Density [gU/cm ³]	1.04	1.04	1.3
²³⁵ U [g/FE]	400	400	400
Plate thickness [mm]	1.33	1.33	> 1.27
Thickness fuel meat [mm]	0.63	0.63	> 0.51
Cladding average/minimum [mm]	0.35/0.25	0.35/0.25	/= 0.38/0.25
Inter-plate water gap [mm]	3.0	3.0	3.0
Outer FE diameter [mm]	38.94	38.94	< 38.58
Outer water gap	3.16	3.16	< 3.52
B (B ₄ C) [g/FE]	-	3.8	3.8
Sm (Sm ₂ O ₃) [g/FE]	-	1.4	1.4
Gd (Gd ₂ O ₃) [g/FE]	2.5	-	-

Hydraulic measurements


At start irradiation campaign: pressure drop as a function of flow



Reactivity evolution as a function of burnup



Azimuthal heat flux distribution COBRA-HEU-LTAs




Feedback new type driver fuel

- Cycle 01/2019: 5 type K fresh elements
 - Burn up end of cycle 9 to 21%
 - Heat flux 130-220 W/cm²
- Cyclus 02/2019: 12 fresh elements type K, 5 elements in second cycle
 - Maximum heat flux 410W/cm² (fresh element in H1c) and 406W/cm² (2nd cycle element in A30)


No failures detected up to now


- Addition of Gd as burnable absorber allows for longer reactor cycle
 - First 5 week cycle of BR2 was performed from March 26 until April 30

Configuration of cycle 02/2019



Configuration of cycle 01/2019





Impact of longer cycle

- More operation days possible with same manipulation effort (1 cycle loading/unloading = +/- 12 days)
- Need for more control / shim rods: less available positions for irradiation devices
 - Compensation by utilization of positions in 200mm channels
- Somewhat larger shift in axial hot spot
 - Lower minimum position of rods due to large amount of burnable absorbers